

Problem with Off-Line Tone Generator

Problem:

It is possible that the updated tone amplitude from Off-Line Tone Generator window will not be properly reflected in the Transmitter Configure shared memory. This will prevent the expected change in the tone amplitude from being implemented. The problem only occurs when the Transmitter Configure window remains open after the disabling of the transmitter.

Workaround:

The Transmitter Configure window must be closed after the transmitter is disabled. Click on the *X hotkey* to completely exit the Transmitter Configure window.